

Metal & Cable Corp., Inc.

9337 RAVENNA ROAD, UNIT C P.O. BOX 117
TWINSBURG, OH 44087
PHONE (330) 425-8455 FAX (330) 963-7246

*****FAILURE TO READ AND FOLLOW INSTRUCTIONS
MAY LEAD TO RISK OF INJURY OR DEATH*****

WARNING

FALL HAZARD

FAILURE TO FOLLOW THIS WARNING MAY RESULT IN SERIOUS INJURY OR DEATH.

Use OSHA approved fall protection equipment when installing mount.

Mount NOT man-rated. Do not lean on mount, hang on mount, or use mount for support.

CAUTION

MAGNET HAZARD

FAILURE TO FOLLOW THIS CAUTION MAY RESULT IN INJURY OR PROPERTY DAMAGE.

Mount contains magnetic components.

- PINCH HAZARD. Interaction with magnets on mount may create a pinch hazard.
- PROPERTY HAZARD. Electronic objects such as cell phones, hearing aids, and beepers may be damaged.

WARNING

DETACHMENT HAZARD

FAILURE TO FOLLOW THIS WARNING MAY RESULT IN SERIOUS INJURY OR DEATH.

Failure to follow installation instructions, including application of correct torque values, may create a mount detachment hazard. Mount must remain tethered to tower at all times.

CAUTION

CUT HAZARD

FAILURE TO FOLLOW THIS CAUTION MAY RESULT IN INJURY.

Metal components of mount may have sharp edges. Use care and wear OSHA approved protective clothing, work gloves, and safety glasses when handling and installing mount.

WARNING

MAGNET HAZARD

FAILURE TO FOLLOW THIS WARNING MAY RESULT IN SERIOUS INJURY OR DEATH.

Mount contains magnetic components. Wearers of cardiac pacemakers, implantable cardioverter defibrillators (ICDs) or other metallic, magnetic, or mechanical implants, devices or objects should not come into contact with mount.

WARNING

Do not install on top of ice.

Metal & Cable Corp., Inc.

9337 RAVENNA ROAD, UNIT C P.O. BOX 117
TWINSBURG, OH 44087
PHONE (330) 425-8455 FAX (330) 963-7246

Installation instructions for Magnemount MMSA-38, or Magnet Assemblies

Do not remove the Poly pads on the bottom of the magnets. They are an integral part of the system!!!

Tools needed: None

- 1) **Do not place on top of a weld.**
- 2) Prior to the installation of the cable holders – DO NOT REMOVE THE ATTACHED BUBBLE WRAP UNTIL THEY ARE ABOUT TO BE INSTALLED.
- 3) Please, wipe the surface on the tank beneath the magnet to maximize the holding power of the magnets.
- 4) Spacing of the MMSA-38 mounts should be 2 feet when mounted vertically, or 3 feet when mounted horizontally.
- 5) When ready to install, remove the bubble wrap and place on the tank.
- 6) There are no adjustments to be made.

Removal

- 1) Pull the adapter to the side to release the magnet.
- 2) Cover the magnet to keep it free of debris.

Any questions at any time, call David Klein at 330-963-7909 (direct)